


1. Short cylindrical center mounting.
2. K13 chucks are matched with stepped jaws.
3. K13- $\phi$  chucks are matched with sloped jaws.
4. Suitable for clamping and machining the thin-walled components.
5. Especially suitable for machining all kinds of cutting tools with handles.

## Characteristic parameters

Size	D	D1	D2	D3	H	H1	h	z-d
4"	100	72	84	26	73	53.5	3.5	3-M8
5"	130	100	115	35	86	60	3.5	3-M8
6"	165	130	145	42	96.5	66.5	4.5	3-M8
8"	200	165	180	65	109	75	5	3-M10
10"	252	206	226	80	120	80	5	3-M12



- 1.Short cylindrical center mounting.
- 2.K13 chucks are matched with stepped jaws.
- 3.K13- $\phi$  chucks are matched with sloped jaws.
- 4.Suitable for clamping and machining the thin-walled components.
- 5.Especially suitable for machining all kinds of cutting tools with handles.

## Characteristic parameters

Size	D	D1	D2	D3	H	H1	h	z-d
4"	100	72	84	26	73	53.5	3.5	3-M8
5"	130	100	115	35	86	60	3.5	3-M8
6"	165	130	145	42	96.5	66.5	4.5	3-M8
8"	200	165	180	65	109	75	5	3-M10
10"	252	206	226	80	120	80	5	3-M12